

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:				
Company	David Shaver Manager			
OGM	Pete Hess Environmental Scientist III			

Q

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Thursday, June 10, 2010
Start Date/Time:	6/10/2010 7:25:00 AM
End Date/Time:	6/10/2010 8:55:00 AM
Last Inspection:	

Inspector: Pete Hess, Environmental Scientist III

Weather: Mostly cloudy, cool; 60's F. InspectionID Report Number: 2388

Types of Operations

Accepted by: jhelfric 6/21/2010

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	100.00
Total Disturbed	78.45
Phase I	
Phase II	
Phase III	

Mineral Ownership

V	Federal		Underground
	State		Surface
	County	✓	Loadout
	Fee	~	Processing
\Box	Other	П	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee continues the process of shutting down the Wildcat Loadout facility; the last train is expected to be shipped on Friday, June 11, 2010.

UtahAmerican Energy, Inc., is in the process of transferring the ownership of the property to InterMountain Power Agency / Los Angeles Department of Water and Power. The Permittee (UEI) needs to address the remaining deficiencies for Division Order DO-04 and obtain Division approval prior to the transfer of C/007/033 to IPA.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Date

Thursday, June 10, 2010



Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Thursday, June 10, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control		✓		
15.	Cessation of Operations	✓		✓	
16.8	Roads: Construction, Maintenance, Surfacing	✓			
16.Ł	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Thursday, June 10, 2010

Page 3 of 3

3. Topsoil

The topsoil pile adjacent to sediment pond "A" needs to have a protective cover. The vegetation which previously existed is gone. The Division suggests that an alternative be investigated.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ponds A-E were observed as dry. The inlet on the SE corner of Pond "C" needs repairs made to the ditch, and the half-round culvert. Erosion of the ditch and pipiong beneath the half-round have recently occurred.

4.d Hydrologic Balance: Water Monitoring

The Permittee notified the Division on May 24th that the first quarter of 2010 water monitoring data for the Wildcat Loadout permit area had been inserted into the data base "pipeline", and same was ready for uploading to the permanent data base. The Permittee continues to meet this Special Condition of the State issued R645 permit.

7. Coal Mine Waste, Refuse Piles, Impoundments

A few waste piles need to be spread and compacted on the southern end of the pile. A minor berm breach should be repaired on the SE corner. Mr. Shaver agreed to address this issue. All outslopes appear stable. No water is impounded on the active lift. There are no indications that spontaneous combustion is occurring. Noncoal waste was not visible within the placed material.

15. Cessation of Operations

See comments under Inspection Report Summary.

21. Bonding and Insurance

The Permittee provided a general liability insurance Acord renewal form to the Division on June 4, 2010. The coverage term is for one year.